

Company Name: The Nuseries Management Company Limited

Inspector Name: K. Zak

Inspection Date: 22 April 2025

Purpose

This site inspection record is used when undertaking regular site inspections and is solely for the purpose of recording and monitoring the common (communal) parts on behalf of the above company.

What Is Included

The below report comments on the general condition of the interior and exterior communal parts (where applicable) as they were found at the time of this inspection.



Please note: This inspection is carried out visually by the property manager or a competent person instructed by the property manager and should not be used for any other purpose than to comment and record the general state and condition of the common (communal) parts that are inspected during a routine site visit. Where further investigation, testing or remedial work is required, a competent person is instructed by the property manager.



BLOCK MANAGEMENT LTD

PROFESSIONAL PROPERTY MANAGEMENT




Internal Inspection	Acceptable	Not Acceptable	N/A	Comments	Action
Entrances (Main doors)	✓			Main entrance doors were secure and operated without issue.	None
Hallway (Communal Lobbies and Stairs)	✓			Hallways and stairs were clean, clear and free from obstructions.	None
Lighting (Standard and Emergency Lighting)	✓			Lighting, including emergency units, is operational with no faults reported.	None
Internal Doors (Compartment Doors)			✓	N/A	None
Cupboard Doors (Electrical Cupboard Doors)	✓			Electrical cupboard doors were secured and free from visible damage.	None
Windows (Communal Windows)	✓			No cracks or defects observed in glass or frames.	None
Signage (Communal Notices)	✓			Building noticeboard was clearly displayed and information was up to date.	None
Additional Comments					None



BLOCK MANAGEMENT LTD

PROFESSIONAL PROPERTY MANAGEMENT

External Inspection	Acceptable	Not Acceptable	N/A	Comments	Action
Exterior Structure (The Building)	✓			No signs of damage or wear were visible on the building's exterior.	None
Guttering (Gutters and Fascia)	✓			Gutters were securely attached and free of debris at time of inspection.	None
Roofing (Tiles and Cladding)	✓			Roofing inspected from ground level – no signs of damage noted.	None
Communal Grounds (Gardens and Common Areas)	✓			Outdoor spaces were accessible and presented in good condition.	None
Bin Store (Waste Disposal Areas)		✓		Bin store door is broken, repair has been scheduled.	Review
Car Park (Vehicle Parking)	✓			Parking area is in good visual and functional condition.	None
Bike Store (Bicycle Areas)			✓	N/A	None
Additional Comments					None

Entrances (Main Doors)	Hallway (Communal Lobbies and Stairs)	Lighting (Standard and Emergency Lights)	Internal Doors (Compartment Doors)
			
Cupboard Doors (Electrical Cupboard Doors)	Windows (Communal Windows)	Signage (Communal Notices)	Additional Photos
			

Exterior Structure (The Building)	Guttering (Gutters and Fascia)	Roofing (Tiles and Cladding)	Communal Grounds (Gardens and Common Areas)
			
Bin Store (Waste Disposal Area)	Car Park (Vehicle Parking)	Bike Store (Bicycle Areas)	Additional Photos
			